## Oil Field Environmental Incident Summary

**Responsible Party:** EOG RESOURCES, INC. **Well Operator:** EOG RESOURCES, INC.

Well Name: PARSHALL 74-2127H

Field Name: PARSHALL Well File #: 27756

Date Incident: 2/12/2015 Time Incident: 10:50 Facility ID Number:

County: MOUNTRAIL Twp: 152 Rng: 90 Sec: 21 Qtr: NW NE

Location Description:

Submitted By: Keith Kallberg Received By:

Contact Person: Keith Kallberg

600 17TH ST STE 1000N DENVER, CO 80202

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

**Distance Nearest Occupied Building:** 

Distance Nearest Water Well:

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: Yes - Within Dike Reported to NRC: No

Spilled Units Recovered Units Followup Units

10 Barrels 10 Barrels 10 barrels

Oil Brine Other

Description of Other Released Contaminant:

Inspected: Written Report Received: 10/29/2015 Clean Up Concluded: 2/13/2015

Risk Evaluation:

Low

Areal Extent:

N/A

## Potential Environmental Impacts:

Low

## Action Taken or Planned:

Well was shutin stopping the release and for repairs. Vac truck was used to remove the free fluid and a hydro excavator removed the affected material. Will wash, flush and rinse the affected area with a hotoiler today and remove the wash fluids.

Wastes Disposal Location: Recovered oil was put back into the tank battery, solids taken to

Newalta disposal at New Town, wash fluids will go to a SWD.

Agencies Involved: TAT and MHA

## **Updates**

Date: 2/13/2015 Status: Reviewed - Assigned to Other Agency Author: Stockdill, Scott

**Updated Oil Volume:** 

**Updated Salt Water Volume:** 

**Updated Other Volume:** 

**Updated Other Contaminant** 

Notes:

According to the incident summary, this spill remained on location. NDIC retains oversight.